

Oil Field Environmental Incident Summary

Incident: 20140821084809 **Date/Time of Notice:** 08/21/2014 08:48

Responsible Party: HESS CORPORATION

Well Operator: HESS CORPORATION

Well Name: TIOGA GAS PLANT

Field Name: TIOGA

Well File #:

Date Incident: 8/20/2014 **Time Incident:** 14:00 **Facility ID Number:** 550014-01

County: WILLIAMS **Twp:** 157 **Rng:** 95 **Sec:** 26 **Qtr:** NE NE

Location Description: Hydrocarbon impacted soil from an unknown source was observed in close proximity to a un-named creek south of the Tioga Gas Plant.

Submitted By: Jason Henry

Received By:

Contact Person: Jason Henry
3015 16TH ST SW STE 20
MINOT, ND 58701

General Land Use: Well/Facility Site

Affected Medium: Soil and Water

Distance Nearest Occupied Building: 0.1 Mile

Distance Nearest Water Well: 0.1 Mile

Type of Incident: Other

Release Contained in Dike: No

Reported to NRC: Yes

	Spilled	Units	Recovered	Units	Followup	Units
Oil	1	Barrels				

Brine

Other

Description of Other Released Contaminant:

Hydrocarbon impacted soil from an unknown source was observed in close proximity to a un-named creek south of the Tioga Gas Plant.

Inspected:

Written Report Received:

Clean Up Concluded:

Risk Evaluation:

Absorbent materials were deployed in the un-named creek adjacent to the area of hydrocarbon stained soil.

Areal Extent:

An area measuring approximately 5 feet by 5 feet of hydrocarbon impacted soil

Potential Environmental Impacts:

Hydrocarbon impacted soil from an unknown source was observed in close proximity to a un-named creek south of the Tioga Gas Plant. Subsurface investigation to commence following utility clearance. Absorbent materials were deployed in the un-named creek adjacent to the area of

Action Taken or Planned:

Hydrocarbon impacted soil from an unknown source was observed in close proximity to a un-named creek south of the Tioga Gas Plant. Subsurface investigation to commence following utility clearance. Absorbent materials were deployed in the un-named creek adjacent to the area of hydrocarbon stained soil. No free product was observed on the water in the creek.

Wastes Disposal Location: At a properly permitted waste disposal facility.

Agencies Involved: North Dakota Dept. of Health

Updates

Date: 8/21/2014 **Status:** Inspection

Author: Roberts, Kris

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

08/21/14 - 17:00 on location. Met with Tesoro reps who believe this line is one of Tesoro's that was purged and abandoned years ago. Viewed area of impact. Very small area of only a few square feet of creek surface with film and sheen. Multiple absorbent booms have been placed to ensure no downstream migration. Depending on the weather, Tesoro will open the creek bank at the stained location and determine the situation on 8/22/14.

Date: 8/21/2014 **Status:** Correspondence

Author: Stockdill, Scott

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Call from company contact 9:09 8/21/2014.

Company is currently waiting on ND One Call. Company is going to begin excavation and delineation of the site as soon as possible.

Followup is necessary.

Date: 8/21/2014 **Status:** Reviewed - Follow-up Required

Author: Stockdill, Scott

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

According to the incident summary, this spill can possibly impact waters of the state. Followup is necessary.